

B371/374 CLOSURE PROJECT

WEEKLY STATUS MEETING

9:30 am T371Z

AGENDA

February 2, 2005

D&D – Jim Floerke


WASHINGTON GROUP – Dan Coyne

FINAL SURVEY – Jay Britten/Bob Kury

- Rev. 1 of the Building 371/374 Characterization Plan

ACTION ITEMS –

- Walkdown/discussion (conducted on 1/31/05) regarding contaminated areas within Phase 2 (e.g., Room 4101 – drains and bermed area); contact record to follow once Phase 2 characterization is complete.



ADMIN RECORD

B371-A-000253

B371 Project
Weekly Meeting 2/2/2005

Set/Area	D&D Status Jim Floerke			
Area AA	<ul style="list-style-type: none">• Removing Zone 1 duct Rooms 1117/2327; completed in 1115, 1105, 1103, and 1003.• Removing Zone 1 duct Room 2217, 2221 and associated hallway.			
Area AB	<ul style="list-style-type: none">• No activity.			
Area AD	<ul style="list-style-type: none">• Removing Zone 1 duct Room 2325 (one pass through to 2327 left).• Zone 1 duct removed from Room 2203.			
Area AE	<ul style="list-style-type: none">• Removing Zone 1 duct Rooms 2310.• Removing Zone 1 duct Rooms 2306.			
Area AF	<ul style="list-style-type: none">• No activity.			
Duct Removal Summary	<ul style="list-style-type: none">• Main floor – 100% complete• Basement - 83% complete (7,996 of 9,689 linear feet removed)• Sub-basement - 94% complete (903 of 942 linear feet removed)			
<u>Washington Group Activities</u> Dan Coyne				
<table><tr><td><ul style="list-style-type: none">• Sets 1 and 2: Mechanical (piping) removal.• Set 3/4/5: No activity.• Set 6: Continued dry decon (rooms 3563/3561A/3559/3553). Continued mechanical removal (supports/metal partition).• Set 7: Final clean up and punchlist (core drills) for final survey.• Set 8: All activity complete.• Set 9: Mechanical removal (duct in room 1216).• Set 10: No activity.• Set 12: Mechanical and wall removal (rooms 1115/1111/1121/1123 duct/piping/supports).• Set 13: No activity.• Set 14: No activity.• Set 16/17: Continued wall demo.</td><td><ul style="list-style-type: none">• Set 23: Continued punchlist items (platform removal).• Set 24/25: No activity.• Set 29: No activity.• Set 30: No activity.• Set 38: Electrical removal (duct interference). Continued piping draining/removal for duct interference. Continued zone II duct removal for interference with zone I.• Set 39: Performed electrical and mechanical (piping/duct/) removal.• Set 40: Commenced FP-125A plenum removal.• Set 41/46: No activity.• Set 50: No activity.• Area AP: Performing piping & electrical removal and dry decon.• Temporary electrical power maintenance. Continued temp. chiller mechanical installation.• Completed Cold & Dark plan implementation.• Commenced bldg. 374 demo.• Continued mechanical & electrical isolation of T-Gen.</td></tr></table>			<ul style="list-style-type: none">• Sets 1 and 2: Mechanical (piping) removal.• Set 3/4/5: No activity.• Set 6: Continued dry decon (rooms 3563/3561A/3559/3553). Continued mechanical removal (supports/metal partition).• Set 7: Final clean up and punchlist (core drills) for final survey.• Set 8: All activity complete.• Set 9: Mechanical removal (duct in room 1216).• Set 10: No activity.• Set 12: Mechanical and wall removal (rooms 1115/1111/1121/1123 duct/piping/supports).• Set 13: No activity.• Set 14: No activity.• Set 16/17: Continued wall demo.	<ul style="list-style-type: none">• Set 23: Continued punchlist items (platform removal).• Set 24/25: No activity.• Set 29: No activity.• Set 30: No activity.• Set 38: Electrical removal (duct interference). Continued piping draining/removal for duct interference. Continued zone II duct removal for interference with zone I.• Set 39: Performed electrical and mechanical (piping/duct/) removal.• Set 40: Commenced FP-125A plenum removal.• Set 41/46: No activity.• Set 50: No activity.• Area AP: Performing piping & electrical removal and dry decon.• Temporary electrical power maintenance. Continued temp. chiller mechanical installation.• Completed Cold & Dark plan implementation.• Commenced bldg. 374 demo.• Continued mechanical & electrical isolation of T-Gen.
<ul style="list-style-type: none">• Sets 1 and 2: Mechanical (piping) removal.• Set 3/4/5: No activity.• Set 6: Continued dry decon (rooms 3563/3561A/3559/3553). Continued mechanical removal (supports/metal partition).• Set 7: Final clean up and punchlist (core drills) for final survey.• Set 8: All activity complete.• Set 9: Mechanical removal (duct in room 1216).• Set 10: No activity.• Set 12: Mechanical and wall removal (rooms 1115/1111/1121/1123 duct/piping/supports).• Set 13: No activity.• Set 14: No activity.• Set 16/17: Continued wall demo.	<ul style="list-style-type: none">• Set 23: Continued punchlist items (platform removal).• Set 24/25: No activity.• Set 29: No activity.• Set 30: No activity.• Set 38: Electrical removal (duct interference). Continued piping draining/removal for duct interference. Continued zone II duct removal for interference with zone I.• Set 39: Performed electrical and mechanical (piping/duct/) removal.• Set 40: Commenced FP-125A plenum removal.• Set 41/46: No activity.• Set 50: No activity.• Area AP: Performing piping & electrical removal and dry decon.• Temporary electrical power maintenance. Continued temp. chiller mechanical installation.• Completed Cold & Dark plan implementation.• Commenced bldg. 374 demo.• Continued mechanical & electrical isolation of T-Gen.			

**B371 Project
Weekly Meeting 2/2/2005**

Final Survey – Jay Britten					
Phase I			Phase II		
B374	Total Scan m² Required	Scan m² Completed	B371	Total Scan m² Required	Scan m² Completed
Class I	1,773	1,773	Class I	TBD	TBD
Class II	2,658	2,658	Class II	TBD	TBD
Class III	53	53	Class III	TBD	TBD
	Total m² Complete:	4,484		Total m² Complete:	TBD
	% Complete:	100%		% Complete:	0%
DOP Surveys	Total Scan m² Required	Scan m² Completed			
Survey Area A	1,150	1,150			
	% Complete:	100%			
Phase III			Phase IV		
B371	Total Scan m² Required	Scan m² Completed	B371	Total Scan m² Required	Scan m² Completed
Class I	N/A	N/A	Class I	12,910	0
Class II	N/A	N/A	Class II	10,270	0
Class III	TBD	TBD	Class III	63	0
	Total m² Complete:	TBD		Total m² Complete:	0
	% Complete:	0%		% Complete:	0%